


# BOILER FEED PUMP



y: Distance between Motor Shaft and Pump Shaft

Size	DNd	DNs	a	b	c1	f	h1	h2	m1	m2	n1	n2	e1	e2	s1	s2	w	d	l	t	u
3216	32	50	80	50	17	360	132	160	100	70	240	190	110	140	15	14	260	24	50	27	8
3220			160				180														
4016	40	65	132				160														
4020							180														
5016	50	80	100	65	17	360	160	200	125	95	320	250	110	140	15	14	260	24	50	27	8
5020			200				212														
6516	65	100	280																		
6520							180	225													
8016	80	125	125																		

Ask SCARDANA about all pump replacements

## SCARDANA®

DIVISION OF SCARDANA CORPORATION

Toll free Fax : (1) - 877 - 228 - 9879

FAX: (1) - 450 - 671 - 3898

TEL: (1) - 450 - 465 - 2480

E-mail : sales@scardana.com

Web : www.scardana.com